



ROOM 4311, U.S. DEPARTMENT OF INTERIOR FLAT FILES

PHOTO # 25



ROOM 4210, VISIBLE DEFLECTION IN TOPS
OF CONFERENCE TABLES ALONG WALL

PHOTO # 26



ROOM 3415, DEFLECTION EVIDENT IN FLOOR
DUE TO GAPS BETWEEN CABINETS

PHOTO # 27



ROOM 3415, DEFLECTION EVIDENT IN FLOOR DUE TO
GAPS BETWEEN CABINETS

PHOTO # 28



ROOM 3415, DEFLECTION EVIDENT IN FLOOR
DUE TO GAPS BETWEEN CABINETS

PHOTO # 29



ROOM 3415, DEFLECTION EVIDENT IN FLOOR
DUE TO GAPS BETWEEN CABINETS

PHOTO # 30



ROOM 3415, DEFLECTION EVIDENT IN FLOOR
DUE TO GAPS BETWEEN CABINETS

PHOTO # 31



ROOM 3301, SAFE NEXT TO COLUMN, SOIL
CONSERVATION SERVICE AREA

PHOTO # 32